

S a f e t y D a t a S h e e t

Company name : TERAOKA SEISAKUSHO CO., LTD.
Address : 1-4-22 Hiromachi, Shinagawa-ku, Tokyo 140-8711, Japan
Department : Quality Assurance Department
Telephone : 03-3491-0837

Issued : June 9, 2017
Revised : March 11, 2019

1. Product name : Anti-slip tape No.953

2. Hazards identification

GHS Classification : Not applicable to classification standard (because our product is "Article")
Specific hazards : This product contains epoxy resin defined as mutagen.
Bisphenol A type liquid epoxy resin
CAS No.25068-38-6

3. Composition, information on ingredients

Single material or mixture : Mixture material
Component : Artificial grain + Bond / Aluminum foil / Acrylic adhesive / Release liner
Chemical formula, CAS No. : Not identifiable, because of mixture of several materials
Pollutant Release and Transfer Register Laws (in Japan)
Class 1 Designated Chemical Substances : Not contained
Class 2 Designated Chemical Substances : Not contained

4. Emergency measures

If entered into eyes : Wash with clean running water and consult the doctor.
If affixed to the skin : It is recommended to peel off slowly and then wash with soap and water.
If swallowed : Consult the doctor immediately.

5. Measures against fire

Extinguishing method : According to the common method.
Extinguisher : Water, general use fire extinguisher (powder, bubble, carbonic acid gas)

6. Measures against leakage

No leakage.

7. Precautions in handling and storage

Handling : Neither there is danger nor harmfulness, except that the tape is heavy weight.
Storage : Avoid direct sunlight, high temperature and humidity.

8. Exposure controls, personal protection

Density to be controlled : Not specified.
Tolerance of density : For Japan Industry Hygienic Institute ... Not specified.
For ACGIH ... Not specified.
Equipment to be provided : Generally not necessary.
Protective tool : Not necessary.
